

November 14, 2003

Ms. Kathleen DeMeter, Esq.
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

03V-442
Revised

Re: Defect Information Report
Number: 034ZND0139 Rv. 1

Ms. DeMeter:


In accordance with the provisions of 49 CFR Part 573.5(b) Defect and Noncompliance Reports, Mitsubishi Motors North America, Inc. (MMNA) hereby furnishes this revised Defect Information Report, which contains details of a defect in a limited number of 2003 and 2004 model year MMNA manufactured vehicles.

This revision to MMNA Report # 034ZND0139 reflects additional and/or updated information that has become recently available. In summary, MMNA has broadened the scope of this voluntary action to identify defective parts in vehicles from the earliest known time of manufacture. Also, the proposed remedy has changed to include replacement of the fuel pump assembly on vehicles identified with the condition in lieu of the previously planned modification.

Again, each distributor will advise you of their launching schedule and provide copies of the Owner Notification Letter, Service Bulletin and all other pertinent information prior to customer notification.

If you have any questions, please feel free to contact me at (309) 888-8900 or Mr. J. Bachman at (309) 888-8943.

Sincerely,



Jerry Berwanger
Senior Vice President - Quality
Mitsubishi Motors North America - Mfg. Div. (MMNA)

Attachment: DIR Rv. #1

Defect Information Report for,
Number:

Mitsubishi Motors North America, Inc. - Mfg. Div.
034ZND0139 Rv.1

1. The manufacturer's name:

**Mitsubishi Motors North America, Inc. - Manufacturing Division
100 N. Mitsubishi Motorway
Normal, Illinois 61761**

2. Identification of the vehicles and defect item:

Make	Line	Model Year	Dates of Manufacture
Mitsubishi	Galant	2003	2003-7-16 ~ 2003-9-11
Mitsubishi	Eclipse	2004	2003-7-16 ~ 2003-9-11
Mitsubishi	Eclipse Spyder	2004	2003-7-16 ~ 2003-9-11
Chrysler	Sebring Coupe	2004	2003-7-16 ~ 2003-9-11
Dodge	Stratus Coupe	2004	2003-7-16 ~ 2003-9-11

3. Total number of vehicles:

Make	Line	Model Year	Volume
Mitsubishi	Galant	2003	8,559
Mitsubishi	Eclipse	2003	454
Mitsubishi	Eclipse	2004	1,685
Mitsubishi	Eclipse Spyder	2003	271
Mitsubishi	Eclipse Spyder	2004	927
Chrysler	Sebring Coupe	2003	104
Chrysler	Sebring Coupe	2004	1,218
Dodge	Stratus Coupe	2003	238
Dodge	Stratus Coupe	2004	3,347
TOTAL =			16,803

4. Percentage of vehicles estimated to contain the potential defect:

It is impossible to estimate the actual number of vehicles that contain the defect, however; owners of all potentially affected vehicles will be notified, and those vehicles will be included in this campaign.

5. Description of the defect including summary:

The fuel return line hose fitting on the electric fuel pump may be restricted, causing excessive fuel pressure to build up in the fuel injection system. Excessive fuel pressure may result in the fuel return hose becoming dislodged, resulting in fuel leakage. Fuel leakage in the presence of an ignition source could result in a fire.

6. Chronological summary of events leading to this determination:

A routine Mitsubishi in plant audit of a vehicle revealed a slight driveability issue which resulted in the replacement of the fuel pump. A field report of excessive fuel pressure led to the return of several fuel pumps. These electric fuel pumps were returned to the supplier for investigation. It was found that a piece of plastic flashing in the fuel pump return line fitting was obstructing the return line opening, resulting in excessive fuel pressure. A report from the field of fuel leakage from a rental car company led to this determination.

7. Test results for a noncompliance:

Not applicable.

8. Description of the proposed remedy:

Owners of all affected vehicles will be notified and encouraged to bring their vehicles in for inspection of the fuel return line and fitting for blockage. Those vehicles exhibiting blockage of the fuel return port will receive a replacement fuel pump.

9. Launch date:

The estimated launch date for customer notification is December 2003, when an appropriate supply of parts becomes available and the customer notification letters and service bulletin are completed.

10. Notices, bulletins and communication:

Copies of the owner letters, bulletins will be provided as soon as they are available.

Any owners that may have already paid to have this condition corrected will be directed to call the appropriate customer relations hot line phone number.

**Jerry Berwanger, Senior Vice-President - Quality
Mitsubishi Motors North America - Manufacturing Division
100 N. Mitsubishi Motorway
Normal, Illinois 61761
Phone: 309-888-8900 Fax: 309-888-7202
E-mail: jerry.berwanger@mma-bn.com**